

NT630 PIUS FAQ

About Register&Update:

- The newer version requires no registration.
- Supports updates via 2.4GHz WiFi.
- No subscription needed—enjoy lifetime free updates.

Reset Function does not Work:

(Ensure car faults are repaired before performing the reset functions)

1. Cannot reset airbag crash/collision codes. Not support programming.
2. Some vehicles only support manual bleed, so the ABS auto bleed function will not work on these models. For CHRYSLER/JEEP/DODGE vehicles, the auto bleed function works only on the right side; the left side requires manual bleed. (If you can not make sure, please confirm with us BEFORE purchase!)
3. Older vehicles without electronic parking systems cannot perform EPB reset. Some functions may be unavailable if the vehicle lacks the necessary components.

Auto VIN does not Work:

1. Ensure the ignition is turned on.
2. Confirm the OBD2 diagnostic cable is securely connected to the DLC port.
3. Auto VIN feature is available for 99% cars. For some vehicle models that do not support Auto VIN detection, you can enter the VIN manually.
4. If takes long time to get the VIN code automatically, please input the VIN manually.

Car Faults not Fixed:

This car diagnostic scan tool reads error codes and helps identify vehicle issues. However, it can only clear error codes and turn off warning lights after the faults are repaired or maintenance is completed.

About Connection Cable:

The package box includes only the 16-pin OBD2 diagnostic cable. Some vehicles may require special adapters or protocols, such as the Chrysler 12+8 Adapter or the Dodge CCD adapter (please note, our scan tool do not support the CCD protocol).